



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: October 21, 2008

Reviewed: 

Mine Name: Expectation	Permit Number: S/035/0024
Operator Name: Mark Miller	Inspection Date: 10/16/2008
Inspector(s): Brett Gregory for Leslie Heppler 	Time: 12:00 am
Other Participants: None	Mine Status: Suspended

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$3,000

Permit fee: Delinquent 2006-2008.

Purpose of Inspection: This was a follow up inspection to validate if the machinery left on site had been removed. The previous inspector noted that the operator had been notified of the liability for the machinery.

Inspection Summary: Photos attached.

- 1) The permit fees for the last three years have not been paid. The cumulative amount is \$450.00.
- 2) The backhoes need to be removed from the site along with the tracks and any trash.
- 10) There is a considerable amount of vegetation that has grown-in very well since reseeding the area. Re-vegetation is approaching the 70% minimum requirement for bond release.

Conclusions and Recommendations: The equipment must be removed and all fees paid. DOGM will continue to monitor this site until these issues are resolved.

Inspector's Signature 

EC:GVS

cc: Mark Miller

O:\M035-SaltLake\S0350024-Expectation\inspections\insp-10162008.doc



Both trackhoes.



No tracks on backhoe.



Tracks.



Possible toxic barrel.



East view



View



View



Product found on site